
Textron (Beech) A36

Airworthiness Directives
Compliance Report

Propeller: Hartzell PHC-C3Y Series Engine: Continental IO-550-B Airframe: Textron (Beech) A36 Date: 4/29/2025 S/N: E-2426 S/N: QG1090B S/N: 686117 Tail #: N3084Z Hours: Hours: Hours:

AD# Eff Date Subject	Date/Hours	Method of	Rec	Date/Hours	Signature and
Category	at Compliance	Compliance		Next Due	Number
93-24-03 Rudder Forward Spar 01/21/94	05/17/23 2652.20° HOBBS	BBS Previously Complied With	Yes*	Yes* 3152.20 HOBBS	Stephen Ripley 3806161 IA
	05/17/22 2552 20	Downlind With	X ₀	3152 20 HORRS	Stanhan Binlay
04/07/95 Airframe	HOBBS				3806161 IA

AD# Eff Date Subject Category	Subject	Date/Hours Method of at Compliance Compliance	Method of Compliance		Rec	Date/Hours Next Due	Signature and Number
76-07-12	10-357XXX, 10-126XXX, 10-157XXX - 05/01/25 2726.50	05/01/25 2726.50		Operational	Yes	2826.50 HOBBS	Stephen Ripley
08/30/77	08/30/77 Switch Repair or Replacement	HOBBS	Test				300010117



Airworthiness Directives Compliance Report

Hours:

Date: 4/29/2025 Tail #: N3084Z Airframe: Textron (Beech) A36 S/N: E-2426

S/N: 686117 Engine: Continental IO-550-B Hours: S/N: QG1090B Hours: Propeller: Hartzell PHC-C3Y Series

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
70-12-02 06/09/70 Airframe	Center Seat Tracks	A ser a series of contracts	N/A by Serial No.	mandar.		Stephen Ripley 3806161 IA
71-24-10 08/01/73 Airframe	Security of Control Wheel	Antonia de la Caración de Cara	N/A by Serial No.	20 10 mm		Stephen Ripley 3806161 IA
72-11-02 05/20/72 Airframe	Engine Fuel Interruption	A	N/A by Serial No.	a second		Stephen Ripley 3806161 IA
73-14-03 07/06/73 Airframe	Landing Gear Shock Strut Piston	and the second s	N/A by Serial No.		And the second of the second	Stephen Ripley 3806161 IA
74-03-02 02/05/74 Airframe	Landing Gear Strut Pistons	State Stray Color get state i supringational securior sec	N/A by Serial No.	-	product to the distribution of the response	Stephen Ripley 3806161 IA
74-12-02 06/05/74 Airframe	Aft Facing Seats	State State province on the state of	N/A by Serial No.	and an experience of the second secon	0-000-00 b m	Stephen Ripley 3806161 IA
74-24-03 11/22/74 Airframe	Strobe Light System	Curta H	N/A by Serial No.		, 7 & 22 Y . A. 6	Stephen Ripley 3806161 IA
75-05-02 02/21/75 Airframe	Engine Oil	21.09	N/A STC Not Installed	Appropriate Consequence of the C	The whoe yether	Stephen Ripley 3806161 IA
76-22-02 06/02/77 Airframe	Lap Belt Assembly	Contract that tender table is the absorber	N/A by Serial No.	appropriate from the con-	Compromise the first in the second section of the sec	Stephen Ripley 3806161 IA
	Screws in the Control System		N/A by Serial No.	Se obs or	Market Comments of the Comment	Stephen Ripley 3806161 IA
	Window Emergency Egress		N/A by Serial No.		The state of the state of	Stephen Ripley 3806161 IA
	Seat Recline Actuator Handle	a Falls on	N/A by Serial No.	regress of	or as direction of the majority and the state of the stat	Stephen Ripley 3806161 IA
	Firewall Material	ANN STATE	N/A by Serial No.	100.71		Stephen Ripley 3806161 IA
	Seat Tracks	which defined the second of th	N/A by Serial No.	to the second		Stephen Ripley 3806161 IA
	Elevator Trim Tab Actuators	and the second	N/A by Serial No.		1917 a 217 15 16	Stephen Ripley 3806161 IA
91-20-08 10/31/91 Airframe	Fresh Air Blower Housing	05/14/91 503.10 HOBBS	Previously Complied With		Epital management	Stephen Ripley 3806161 IA
92-18-11 10/18/92 Airframe	Landing Gear Circuit	05/18/92 756.00 HOBBS	Previously Complied With		The second of th	Stephen Ripley 3806161 IA
93-03-02 03/12/93 Airframe	Loran Receiver System	2 (%	Previously Complied With		20.00	Stephen Ripley 3806161 IA
93-24-03 01/21/94 Airframe	Rudder Forward Spar	05/17/23 2652.20 HOBBS	Previously Complied With	Yes*	3152.20 HOBBS	Stephen Ripley 3806161 IA
95-04-03 04/07/95 Airframe	Wing Carry Through Frame Inspection	05/17/23 2652.20 HOBBS	Previously Complied With	Yes	3152.20 HOBBS	Stephen Ripley 3806161 IA
97-14-15 09/02/97 Airframe	Cabin and Utility Door Handle	07/24/98 1430.90 HOBBS	Previously Complied With	Marin - India		Stephen Ripley 3806161 IA
99-09-15 05/18/99 Airframe	Flight Control Mechanism		Previously Complied With	1 1		Stephen Ripley 3806161 IA
2000-20-14 11/28/00 Airframe	Firewall Seal	and the second second second second	Previously Complied With	Michigan di sa	*** *** **** ****	Stephen Ripley 3806161 IA





2000-24-04 01/05/01 Airframe	Rudder Control Cable System		Previously Complied With	3CA/	Stephen Ripley 3806161 IA
2001-08-08 06/07/01 Airframe	V-Band Exhaust Clamp	application of the section of the	N/A No Turbo Installed		Stephen Ripley 3806161 IA
2001-11-03 07/20/01 Airframe	Blower Motor Circuit		N/A by Part No.	60 Ale	Stephen Ripley 3806161 IA
2001-23-10 12/13/01 Airframe	Flap Flex Shaft		N/A by Serial No.	8/8/10/10/19	Stephen Ripley 3806161 IA
2003-01-01 02/27/03 Airframe	Right Hand Fuselage Panel	09/10/03 1831.00 HOBBS	Previously Complied With	IEA (does):	Stephen Ripley 3806161 IA
2007-08-08 05/25/07 Airframe	Landing Gear Uplock Rollers	Serve No.	N/A by Serial No.	And the second s	Stephen Ripley 3806161 IA
2008-13-17 08/06/08 Airframe	Circuit Breaker Toggle Switch	11/24/10 2033.70 HOBBS	Previously Complied With		Stephen Ripley 3806161 IA
2009-25-01 01/08/10 Airframe	Pilot & Copilot Shoulder Harnesses	05/01/25 2726.50 HOBBS	C/W by Inspection	2 . 24.0 . 23.2	Stephen Ripley 3806461 IA
2019-23-10 11/22/19 Airframe	Right Aileron Flight Control Cable End Fittings	Est the NG,	N/A by Serial No.		Stephen Roley 38064614A
2023-09-09 07/17/23 Airframe	Exhaust Tailpipe V-Band Coupling	1961 197 62	N/A No Turbo Installed	La Ray Nove - 1912 give	Stephen Ripley 3806161 IA

Engine: Con	tinental IO-550-B		Ag World			and the same
AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
86-13-04 R3 02/24/88 Engine	Cylinder Assemblies Pressure Test	belinted told C	N/A by Serial No.	Free Strategister graduate	.0.	Stephen Ripley 3806161 IA
87-14-02 10/05/87 Engine	Starter Adapter Shaftgear	The second secon	N/A by Serial No.	on a politica or	200 x 200 50	Stephen Ripley 3806161 IA
88-03-06 04/15/88 Engine	Oil Filter	26. 10 eS	N/A by Part No.	rodi	2 (21) 200 17	Stephen Ripley 3806161 IA
88-17-03 08/10/88 Engine	Starter Adapter Assembly	Serel vo.	N/A Not Air Conditioned		VI EMBORIA I	Stephen Ripley 3806161 IA
91-19-03 09/29/91 Engine	Collapsed Oil Filter Elements	evilence.	N/A Filter Date Code		H was to anite	Stephen Ripley 3806161 IA
93-10-02 08/12/93 Engine	Missing Cylinder Valve Retainer Key	Berlal No	N/A by Serial No.		to restatil e	Stephen Ripley 3806161 IA
93-16-15 12/14/93 Engine	Fuel Pump Drive Shaft	sy' turn 8	N/A Engine OH/REMAN Date		15.00	Stephen Ripley 3806161 IA
98-01-08 12/23/97 Engine	Exhaust Roller Rocker Arms	.00° top of	N/A by Part No.		Borah ast rent vo	Stephen Ripley 3806161 IA
99-19-01 09/30/99 Engine	Crankshaft Cheek Cracks	TO A TO CONTRACT OF THE	N/A Engine OH/REMAN Date		And Princes of the American	Stephen Ripley 3806161 IA
2000-23-21 12/12/00 Engine	Crankshaft Connecting Rod Journal Failure	645-5-17A	N/A Engine OH/REMAN Date		of the Continue	Stephen Ripley 3806161 IA
2004-08-10 05/05/04 Engine	ECi Reciprocation Engine Cylinder Head Cracks	The bearing the	N/A STC Not Installed		to make 8 towns of Pi	Stephen Ripley 3806161 IA
2007-04-19 R1 05/07/07 Engine	Superior Air Parts Cylinder Assemblies	West of the	N/A by Part No.	-	Boll ready	Stephen Ripley 3806161 IA
2009-19-07 10/07/09 Engine	EQ3 Cylinder Head Cracks	A 100 00 10	N/A by Part No.	e her s	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Stephen Ripley 3806161 IA
2010-11-04 06/16/10 Engine	Hydraulic Lifter Face Wear	201000	N/A by Part No.	ofty.	HOLD VICE VI	Stephen Ripley 3806161 IA
2012-03-06 02/24/12 Engine	AVStar Fuel Servo Diaphragm		N/A by Part No.		and the same	Stephen Ripley 3806161 IA
2014-05-29 04/25/14 Engine	SA52000-Axxx, SA55000-A1, and SA55000-A20P - (SAP) Cast Cylinder Assemblies	77-2-51	N/A by Part No.		5. 6.3	Stephen Ripley 3806161 IA

))

2016-16-12 09/15/16 Engine	AEC/CMI Cylinder Assemblies		N/A by Part No.			Stephen Ripley 3806161 IA
2022-16-03 08/15/22 Engine	S-1200 Series Magneto Roller Bearings		N/A by Part No.			Stephen Ripley 3806161 IA
2023-02-12 02/17/23 Engine	Intake Valve Failures		N/A by Part No.	2.		Stephen Ripley 3806161 IA
2023-05-16 03/15/23 Engine	Crankshaft Counterweight Retaining Rings		N/A by Serial No.			Stephen Ripley 3806161 IA
2023-09-09 07/17/23 Engine	Exhaust Tailpipe V-Band Coupling	Drak	N/A No Turbo Installed			Stephen Ripley 3806161 IA
2023-17-04 10/26/23 Engine	Oil Filter Adapter Gasket		N/A STC Not Installed		-, +	Stephen Ripley 3806161 IA

Propeller: H	artzell PHC-C3Y Series			1	11	2 4 7
AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
94-17-13 09/15/94 Propeller	Propeller Hub Grease Fitting Hole Cracks		N/A by Serial No.	No to		Stephen Ripley 3806161 IA
2001-07-03 06/04/01 Propeller	BASCO Serviced Propellers	the second distribution of the second	N/A Not Worked by Stated Vendor	t with profess with	e de la composição de la c	Stephen Ripley 3806161 IA
2003-13-17 07/18/03 Propeller	T and W Serviced Propellers		N/A Not Worked by Stated Vendor	-		Stephen Ripley 3806161 IA
2005-14-11 08/17/05 Propeller	Southern California Propeller Serviced Propellers	dispression to the state of the	N/A Not Worked by Stated Vendor	china e espel		Stephen Ripley 3806161 IA
2006-24-07 01/03/07 Propeller	Oxford Aviation/CSE Aviation Serviced Propellers	The state of the s	N/A Not Worked by Stated Vendor	r servicije (rij	Martin or Alberto Paris I (San I Asha)	Stephen Ripley 3806161 IA
2007-26-09 01/30/08 Propeller	Fatigue Cracks		N/A by Blade Serial No.	Tables de la	Notice the protection by the contract of the	Stephen Ripley 3806161 IA

AD# Eff Date Subject Category	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
76-07-12 08/30/77 Switch Repair or Replace Appliance		Complied with By Operational Test	Yes	2826.50 HOBBS	Stephen Ripley 3806161 IA