

FAA -PS4R451M

Burlington - Alamance Regional Airport Burlington, NC 27215

Propeller Logbook (336) 227-1467 1-800-334-6437

		& MINOR ADJUSTMENTS	15, ES,
DATE	TACH		
29 DEC. 08		Overhauled (1) Despelles	SIGNATURE
		DROPElER MIN HC	CZYR-1BFSIN CHUU
		1 6 8 8 FORD III OF	152A.A.1
		N FILL SOUND IN SOUND	hub. Ge
		SENSE SING SING SING SING SING SING SING SING	7019
	20-6242-10F CH44516B	Scalar And Trans T	
ERVICEABLE	24-10F 445168	BY KELLER OR CHAIN AND SERVICE NOT THE REPAIR ATION UNDER: 35 DATE Municipal Airporton, NC 27215 100, NC 27215	PS4R451M;
	12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PAGEN SERVE OF THE STATE OF THE	9. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6.
		THE SERVICE OF SERVICE	
T NAME		MPLISHED BY AIRCRAFT PR INED ABOVE WAS SORDANCE WITH BERAL AVIATION NO	STATION
MANUFACTI	No	SCONPLIST Sign High Burling Bu	
	MODEL. PART NO. SERIAL NO. REMARKS: O	では、2000 2000 2000 2000 2000 2000 2000 200	
		AND SEER B SE	

	TACH		
DATE	TIME	DESCRIPTION OF WORK	SIGNATURE
29 DEC. 08		OVERHAUISO (1) PROPEIRE MINHO	220000
		CIW SIB 118E 1867 110	1212-181 SIN CH 445168
		CIW SIB 118F, 136I, 169, 512 61-6 (06-18-15) (07-21-50) TIL	14.245, SIE 152A, A.D. Note
		- aco UTSYAllsel	FACTORI DOWN / / CALL
		AND MATHUELD. BID, DINGE E	7666A-2 *1 5 17519
		a) + 1061.	
		4 & H PROPELLER SERVICE, INC.	
		3439 SOUTH AVIATION DRIVE	
		JURLINGTON MUNICIPAL AIRPORT	
		URLINGTON, N. C. 27215	
		AADEDAID OTATION	
		AA REPAIR STATION PS4R451M	
	1	-800-334-6437	-cell // // // // // // // // // // // // /

Reg: N1967F S/N: 670456 A/C TT: 4975.5

Mod: M20F Tach: 999.7 TSMOH: 0.00

1-Aircraft Propeller inspected in accordance with FAR Part 43 appendix (D).

2-See ATP Airworthiness Directive Compliance Record dated 01/09/2009 for current status, next due date and time.

"I certify that this aircraft propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition."

In 1/1/00 201/09/200

Lynn R Mace AP 3118643 IA

		a WINDH ADJUSTMENTS	
7-1-/4	TACH TIME 1327,7	DESCRIPTION OF WORK SI 100 hr Inspiration 24	GNATURE
DATE	TACH	DESCRIPTION OF WORK PERFORMED	SIGNATURE
SERVICEABLE PART MANUFACTURER HAPT	PART NAME. MODEL MC- 62 YR PART NO. SERIAL NO. CH 445 REMARKS: Overland 150		mate

DATE	TACH	DESCRIPTION OF WORK	
7-1-14	1327,7	100 hr inspection	SIGNATURE - 1 MI

DATE	TACH	DESCRIPTION OF WORK PERFORMED	SIGNATURE
6 May 15		Overhauled (1) propeller m/n HC-C2YR-1BF s/n CH44516B	
		c/w s/b 118F, 136I, s/I 61-61Y, 245, s/I 152A, AD Note	
		(07-26-09). Greased, painted and balanced. Bld. Dwg.#	
		F7666A-2 #1) F7019 #2) F7061.	
		H&H Propeller Service, Inc.	
		3439 S. Aviation Dr.	
		Burlington, NC 27215	
		1-800-334-6437	
		FAA Repair Station PS4R451M	7 muste

5-14-15	TACH TIME 1344,00	DESCRIPTION OF WORK Re-INST NIGGTF after Overham Torgice & Sofri	SIGNATURE 2hm 4P 3118643
8-29-16	1349.9	100 hr / Annual Inspersion	2/m 1/3/18643
9-19-17	1351.8	100 hr 1 Annual Inspector	2Mm- AP 3118843
10-2-18	1387.3	100hr/Annal inspection	Zhm AP 3118143 JA
0-22-19	1420.6	repair small crack in Awd	2 Lpn. 403118643 IA
		bullhand.	

were the size in the size of t

DATE	TACH	DESCRIPTION OF W	ORK		
0/16/50	1467.2	1. 1 1 1	specien	2112	AP 3118043 X
19/21	1501.7	100h-11	15pmen	Zhh	AV 3118643 3
	AGL Aviation 3550 Foothills Morganton No 828-391-8645	C 28655-7717	Model: M Tail: N	ooney 20F 1967F '0456	
Hours: 159 Performed /		as follows per FAR Appx D & Moor ning hardware for cracks and defec	ev M20 100 Havis Ob		
Performed e defects note accessories inspected ar	engine run up, leaked at this time. The will continue to fur	check, systems check and taxi che below statement in no way, implied the control of time after the lay with all applicable Federal Aviating that this engine has been inspection of the condition FND	eck of all systems on s or guarantees that t is inspection, and only	the ground. No leak his aircraft, or engine y states that this airc	s or other s, or raft was

detail of FAR 43(d). Blended blades. Checked all A this propeller has been inspected IAW a 100 hour	AD's through ATP as of 31DEC2023. I certify inspection and was found to be in airworthy
Way 621	Glenn MacDermod 3053427AP
	this propeller has been inspected IAW a 100 hour condition at this time.